
Model 123.190



- 1 Hydraulic oil pump2 Hydraulic oil reservoir
- 3 Levelling valve 4 Pressure reservoir
- 5 Suspension strut 6 Lever on torsion bar
- Connecting bar
- 10 Torsion bar
- 18 Rear spring19 Semi-trailing arm
- 26 Rear axle carrier

- A Suction line, oil reservoir to hydraulic oil pump B1 Pressure line, oil pump to levelling valve Pressure line, levelling valve to pressure reservoir
- B3 Pressure line, pressure reservoir to suspension strut C Return line, levelling valve to oil reservoir

Visual inspection

With engine running, check

Pressure oil punp

Oil supply tank

Level controller

Pressure reservoir

Tube shocks

Line connections

pipes and hoses for chafing, dents, cracks, corrosion as well as leaks

Note: If leak is present check level control system with engine running and with approx. 150 kg load on rear of vehicle.